

ASBESTOS REMOVAL WORK / LICENCE ENQUIRIES FOR COMMERCIAL CUSTOMERS

Enquiries from businesses or builders etc.

The advice given on removal work will depend on the nature of the work and would normally be referred to an Environmental Health Officer from the Food & Safety Team.

Contact: Mr J Blythe, (EHO) Food and Safety Group, South Lakeland House, Lowther Street, Kendal, LA9 4UD. Telephone 01539 733333.
E Mail: foodandsafety@southlakeland.gov.uk

Applying for 'Asbestos Removal Licences' should be made to the Asbestos Licensing Unit (part of HSE) on 0131 247 2135.

The area sites listed below can take **small** amounts of asbestos cement.
[n.b.the sites at Ambleside and Grange-Over-Sands do not accept asbestos waste]

A maximum of:

- 3 bags of waste. [The waste must be double bagged in 1000 gauge polythene, sealed with duct tape and labelled ASBESTOS] or,
- 3 sheets, 1m x 1m double wrapped in 1000 gauge polythene sheet, sealed with duct tape and labelled **ASBESTOS**.

Kendal Area: The C.A.W. Site at Canal Head, Canal Head North, Kendal.
Telephone: 01539 728084.

Ulverston Area: C.A.W. Project Furness, Walney Road, Barrow-in Furness.
Telephone: 01229-823570.